

**Crow Lane Landfill  
Complaint Response Report**

ver. 08/09

Date: <u>9/14/09</u>		Time of Complaint: <u>1:00pm</u>	
Complainant		Response	
Name: <u>Mary Wolf</u>		Time: <u>1:11 pm</u>	
Address <u>126 Zabloskie Dr</u>		By Name: <u>Peter Lislausis</u>	
Odor	YES <input type="radio"/> NO <input checked="" type="radio"/> (circle one)		
Other: _____	Initial: <u>PL</u>		

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
N. side of house	0.001	0.001	0.002	0.001	checked / O filter ok!
Back of house	0.002	0.002	0.002	0.002	

Weather Conditions at time of response: 78°F, Sunny, Lt. wind

Wind: Direction (From) W Speed: 3-6 mph

Was Perimeter Landfill Survey Performed following the complaint? ☒ YES ☐ NO (circle one)

Crow Lane Landfill  
Complaint Response Report

ver. 08/09

Date: <u>9/13/09</u>	Time of Complaint: <u>2:22pm</u>
Complainant Name: <u>Nancy Klodenstad</u>	Response Time: <u>3:30pm</u>
Address: <u>18 Wilkwood Dr</u>	By Name: <u>Pete Helander</u>
Odor YES <input checked="" type="radio"/> NO (circle one)	Initial: <u>PH</u>
Other: _____	

Were odors detected during the response? No

Odor Intensity (1-5 scale) NA Odor Duration: NA

Odor Description/Type: NA

Location	H2S Readings During Response				Comments
Frontal Property	0.001	0.000	0.001		No odor detected

Weather Conditions at time of response: \_\_\_\_\_

Wind: Direction (From) \_\_\_\_\_ Speed: \_\_\_\_\_

Was Perimeter Landfill Survey Performed following the complaint?

YES ☒ NO (circle one)